



Photo S4-1 (June 2009) –
Facing north across the soil
nail repair area in 2009, for
comparison with 2011
conditions (refer to Photo S4-
2).



Photo S4-2 (June 2011) –
Taken from the same location
as Photo S4-1. Landslide
movement has been ongoing,
with continued retrogression
at the slope crest and
disturbance of the erosion
control and bioremediation
techniques by soil flows.



Photo S4-3 (June 2011) –
Facing south at the slide area.
Note the instability in the upper,
steeper portions of the slope.
Retrogression of the slide
continues to occur with large
blocks sliding down and adding
to the slide mass.



Photo S4-4 (June 2011) –
Facing south at recent
retrogressions of the slide scarp
where large blocks have
detached from scarp face. The
blocks detached in late 2010 to
early 2011.



Photo S4-5 (June 2011) –
Taken from near the same location as Photo S4-6. Slide movement has continued in the upper slope. The vegetation cover has become well established on the lower slope. The bank protection remains in good condition.



Photo S4-6 June 2009 –
A view of the site area from 2009, for comparison with Photo S4-5.