



**Photo S8-1 (June 2011)** - Facing north along the west edge of the road surface at the north end of the site. This area had the most significant cracking at the site following a similar pattern as has been observed during previous inspections. The other areas of the site remained mostly unchanged since the previous inspection in June 2011.



**Photo S8-2 (June 2011)** – Facing north from the middle of the site. The cracks in the road surface are relatively minor, and follow a similar pattern as has been observed during past inspections.