



Photo S10A - 1 (June 2011) - Facing north from the south end of the site. The pattern of the cracking in the road surface is similar to the conditions observed in 2010; however, the magnitude of the vertical settlement and crack aperture has increased in comparison to the conditions during previous inspections.