



**Photo S10(C)-1 (June 2011)**

Facing south at the sinkhole formed over the culvert in the west ditch. The sinkhole has expanded in size since it was first identified in 2007.



**Photo S10(C)-2 (June 2009)**

Facing downstream from the culvert inlet, with soil debris from the sinkhole coming through a breach in the top of the culvert faintly visible in the right background.



**Photo S10(C)-3 (June 2011)**

Facing north across the cracking and settlement area of the northbound lane that has formed through repeated overlays since 2003.



**Photo S10(C)-4 (June 2009)**

Facing towards the creek channel downstream of the road culvert (northeast). The creek channel and bank are in approximately the same condition as was observed during the 2008 and 2009 inspections.





**Photo S10(C)-5 (June 2011)**

Facing upstream (southwest) at the west ditch. Note the erosion damage that has apparently worsened in recent years.