



**Photo S22-1 (June 2011)** - Facing west (along the southbound lane) from the east end of the site. The pattern and extent of the cracks in the road surface are similar to what has been noted during past inspections.



**Photo S22-2 (June 2011)** - Facing east (along the southbound lane) from the west edge of the site. The damage to the road surface is similar to that noted in past inspections.