



**Photo 1:** Pavement cracking at east flank of the slide area sealed in 2010



**Photo 2:** Pavement dip in Hwy 39:02 near west flank of slide





**Photo 3:** Sparse riprap armoring at east culvert outlet



**Photo 4:** Inlet of east culvert above base of ditch leading to ponding





**Photo 5:** North sideslope well vegetated



**Photo 6:** Pavement cracking at west flank of slide sealed in 2010



**Photo 7:** Modeste Creek at toe of sideslope protected from erosion with Gabion baskets