



**Photo 1:** Inlet of east culvert above base of ditch leading to ponding



**Photo 2:** East drainage gallery - one of nine drains in operation





**Photo 3:** West drainage gallery - two of nine drains in operation



**Photo 4:** Gabion basket wall located at toe of sideslope adjacent to Modeste Creek. Culvert conveying groundwater from drainage galleries to Modeste Creek.



**Photo 5:** Pavement cracking near west flank of slide sealed in 2010.