



Photo S43-1 (May 2013)

Standing on the southwest road shoulder looking towards the south. The extent of the slide damage within the road surface is outlined in red. The apparent slide direction is shown by the arrow.



Photo S43-2 (May 2014)
Standing in a similar location to Photo S43-1 and looking to the south at the cracking within the southwest road shoulder. The condition was similar to the 2013 inspection.



Photo S43-3 (May 2014)
Standing in the upslope ditch looking towards the west at the slide area indicated between the two red lines. Note the settlement visible along the guardrail.



Photo S43-4 (May 2014)
Standing in the upslope ditch looking towards the southeast up the ditch invert. The area is relatively flat and had ponded water.