



Photo S45-1 (May 2013) – Standing at the creek bank at the east end of the East Site, looking towards the southwest at the bank erosion.



Photo S45-2 (May 2014) – Standing at the creek bank at the east end of the East Site, looking towards the southwest at the bank erosion. Similar location as Photo 1, note the low flow and relatively unchanged bank conditions relative to the 2013 conditions.



Photo S45-3 (May 2013) – Standing on the bank at the west end of the West Site, looking towards the east at the bank erosion.



Photo S45-4 (May 2014) – Standing on the bank at the west end of the West Site (similar location to Photo S45-3), looking towards the east at the bank erosion. Note the increased extent of erosion to the east and number of fence posts undermined relative to the 2013 conditions.



Photo S45-5 (May 2014) –
Standing at the West Site
looking towards the
northeast at the backslope
sliding.