



**Photo S46-1 (2007)**  
At the North Site on the west side of the road embankment looking towards the south at the area where landslide damage had occurred and recently been regraded.



**Photo S46-2 (2013)**  
Standing in a similar location to Photo S46-1 and looking to the south at the area referred to as the North Slide during the 2013 inspection. An arc-shaped crack was observed developing within the road embankment. Note that a guardrail has been installed on the west side of the road since 2007.



**Photo S46-3 (2014)**  
Taken in the same location as the previous photo (S46-2), looking south at the circular earth slide within the road embankment. Note the increased downdrop and downslope displacement relative to the 2013 conditions.



**Photo S46-4 (2013)**  
At the Southern Slide area, standing on the west side of the highway embankment looking towards the south at the headscarp of the landslide that formed within the year. Movement is towards the right side of the photo.



**Photo S46-5 (2014)**  
Standing in the same location as the previous photo (S46-4) looking at the Southern Slide. Note the increased downslope movement of the failed soil mass exposing more soil near the headscarp.



**Photo S46-6 (2014)**  
Near the base of the west side of the road embankment looking upslope towards the northeast at the Southern Slide area.