



**Photo 1:** Recently installed erosion and sediment control at outlet of east culvert



**Photo 2:** West drainage gallery – two of nine running



**Photo 3:** East drainage gallery – zero of nine running





**Photo 4:** Erosion and deformation of gabion baskets along riverbank at toe of slope



**Photo 5:** Ponding water at west culvert outlet





**Photo 6:** Erosion and sediment control installed along drainage path immediately west of the site



**Photo 7:** West culvert inlet protection well vegetated