



**Photo #1** General view of the highway looking east; note the ACP patch placed on the highway surface



**Photo #2** Looking east from the western flank of the landslide at a reflective diagonal crack in the highway EBL (NC58)



**Photo #3** Looking east from the western limit of the landslide at open longitudinal reflective cracks in the highway EBL (NC58)



**Photo #4** Looking east from near the eastern limit the landslide at a longitudinal reflective crack in the highway EBL (NC58)





**Photo #5** Looking west from the eastern flank of the landslide at a reflective diagonal crack in the highway EBL (NC58)



**Photo #6** Looking at voids formed at a few locations along the tops of the piles (NC58)



**Photo #7** Looking east at an open longitudinal crack in the highway WBL (NC58A)



**Photo #8** Looking east at open cracks on the highway surface (NC58A); note existing dip





**Photo #9** Looking west from the eastern flank of the landslide at the dip bounded by the highway cracks (NC58A)