







Well defined ditch on backslope side of highway













Two new unstable areas have appeared with scarps regressing towards the pavement