





























View of new slump section at north end of gravel berm due to June 2005 flooding.
Width is about 13 m.







Ditch spoil pile placed at crest of slope



Backslope Erosion

















Observed cracking in pavement























