


**CENTRAL REGION
LANDSLIDE RISK ASSESMENT
SITE INSPECTION FORM**

| | | | | |
|--|--|---|---|--|
| SITE NUMBER AND NAME C23 H854:01 Erosion | | HIGHWAY & KM | PREVIOUS INSPECTION DATE June 19, 2002 | INSPECTION DATE May 22, 2003 |
| LEGAL DESCRIPTION | NAD 83 COORDINATES N 5839620 E 402103 | RISK ASSESMENT PF: 9 CF: 10 TOTAL: 90 | | |

| | |
|---|--|
| SUMMARY OF SITE INSTRUMENTATION: None | INSPECTED BY:  |
| LAST READING DATE: | |
| PRIMARY SITE ISSUE: Ditch erosion – sediment flowing into Battle River | |
| APPROXIMATE DIMENSIONS: | |
| DATE OF ANY REMEDIAL ACTION: | |

| ITEM | CONDITION EXISTS | | DESCRIPTION AND LOCATION | NOTICABLE CHANGE FROM LAST INSPECTION | |
|-------------------|------------------|----|--------------------------|---------------------------------------|----|
| | YES | NO | | YES | NO |
| Pavement Distress | | | | | |
| Slope Movement | | | | | |
| Erosion | X | | | | X |
| Seepage | | | | | |
| Culvert Distress | | | | | |
| | | | | | |
| | | | | | |

| |
|--|
| COMMENTS |
| Refer to attached photos, previous report and remediation plan |
| |
| |
| |
| |
| |
| |