





















Gabion structure incomplete – rocks can escape from centre section.







Minor rill erosion beyond matting







Upstream end of east ditch















