

Slide Name: (GP 12a) Hwy 49:04 Ksituan River West Slide
Inspection Date: June 22, 2004
Inspection By: Alberta Transportation and EBA staff listed on Page 1

1.0 BACKGROUND

Refer to EBA 2002 and earlier reports for site conditions and details of risk assessment. Previous instrumentation was rendered defunct by 2001 highway widening construction activities. The slide was remediated by toe berming and minor shifting of alignment in 2001.

2.0 OBSERVATIONS

The remediated slide area was visually inspected; no obvious signs of instability were observed.

3.0 RISK ASSESSMENT

Current risk rating is lowered after construction of the slide stabilization measures in 2001 as part of the roadway widening:

$$PF (2) * CF (4) = 8$$

4.0 ACTION

Visual monitoring of this site should continue to assess the performance of the 2001 remediation.