


Looking upgrade north (away from Hwy. 49 Jct.)

- Sideslope slides (right) has encroached to shoulder of northbound lane
- Erosion gully formed at backslope (left) as a result of runoff from upland farm area



Looking west (another view)

- Erosion gully at backslope at upper portion of river valley



Looking downgrade south (toward Ksituan River)

- Sideslope slides to left of photo (no clearly visible from road elevation)
- Backslope slides on right started to develop