

**Slide Name:** (GP 15b) SH 727:02 Ksituan River  
**Inspection Date:** N/A  
**Inspection By:** N/A

## **1.0 BACKGROUND**

Refer to EBA 2000 Report for site conditions and details of risk assessment. SH 727:02 is a gravel road parallel to the Ksituan River with a setback of approximately 20 m from the riverbank at this location. The location was adjoining to the approach fill for a bridge culvert. It was reported by AT in the 2000 inspection that settlement of the road grade was noted after completion of the widening (around 1999); therefore, this site was enlisted for observation of road alignment stability.

## **2.0 OBSERVATIONS**

This site was not inspected and no comment is provided.

## **3.0 RISK ASSESSMENT**

PF (2) \* CF (3) = 6

Risk rating was downgraded after inspections from 2000 to 2003.

## **4.0 ACTION**

- Continue visual monitoring of this area. Maintenance forces are requested to record details of resurfacing (gravel placement) and any occurrence of settlement in the future.
- The site should be inspected in 2005.