



PHOTO 1 EAST CRACK LOOKING WEST



PHOTO 2 EAST CRACK LOOKING EAST

HWY 43:16 - WHITECOURT EAST HILL (NC1)
SELECTED PHOTOGRAPHS

DATE: JUNE 2, 2004
THURBER PROJECT #15-16-192



PHOTO 3 WEST CRACK LOOKING WEST



PHOTO 4 WEST CRACK LOOKING EAST

HWY 43:16 - WHITECOURT EAST HILL (NC1)
SELECTED PHOTOGRAPHS

DATE: JUNE 2, 2004
THURBER PROJECT #15-16-192



PHOTO 5 LOOKING EAST ALONG NORTH GUARDRAIL



PHOTO 6 LOOKING EAST ALONG SOUTH SHOULDER

HWY 43:16 - WHITECOURT EAST HILL (NC1)
SELECTED PHOTOGRAPHS

DATE: JUNE 2, 2004
THURBER PROJECT #15-16-192



PHOTO 7 SUBDRAIN AND CULVERT
OUTLETS NEAR STATION 1+680
(SOUTH OF HIGHWAY)



PHOTO 8 AREA OF PREVIOUS BACKSLOPE REPAIR (LOOKING SOUTHWEST)

HWY 43:16 - WHITECOURT EAST HILL (NC1)
SELECTED PHOTOGRAPHS

DATE: JUNE 2, 2004
THURBER PROJECT #15-16-192



PHOTO 9 TWO EASTERN CRACKS IN NEW ASPHALT TRAIL (LOOKING EAST)



PHOTO 10 EASTERNMOST CRACK IN NEW ASPHALT TRAIL (LOOKING NORTHEAST)

HWY 43:16 - WHITECOURT EAST HILL (NC1)
SELECTED PHOTOGRAPHS

DATE: JUNE 2, 2004
THURBER PROJECT #15-16-192



PHOTO 11 BIN WALL, STATION 1+200 LOOKING NORTHEAST



PHOTO 12 BIN WALL, STATION 1+200 LOOKING WEST

HWY 43:16 - WHITECOURT EAST HILL (NC1)
SELECTED PHOTOGRAPHS

DATE: JUNE 2, 2004
THURBER PROJECT #15-16-192