



NC1 - WHITECOURT EAST HILL
2013 Annual Inspection Photos



PHOTO 1: Dip in pavement at Catch Basin Cracks.



PHOTO 2: Catch Basin Cracks, facing East.



PHOTO 3: East Cracks, facing West.



PHOTO 4: West Cracks, facing North.



PHOTO 5: East end of surficial slope movement in Hwy 43 backslope (Approx. Sta. 1+600).



PHOTO 6: Toe bulge of surficial slope movement in Hwy 43 backslope (Approx. Sta. 1+600).




PHOTO 7: Spring observed at base of tree, standing water, facing upslope.



PHOTO 8: Seepage in North embankment slope at approximately Station 1+950.



PHOTO 9: Concrete spillway and culvert at approximately Station 1+650.



PHOTO 10: Culvert outlet at approximately 1+650.



PHOTO 11: Half round surface culvert, North side of Hwy 43, facing East.