



PHOTO 1 LOOKING EAST ON WESTBOUND LANES AT THE LOCATION OF ROADWAY WEST CRACK



PHOTO 2 LOOKING EAST ON WESTBOUND LANES AT THE LOCATION OF ROADWAY EAST CRACK



PHOTO 3 LOOKING WEST AT POTENTIALLY UNSTABLE AREA DOWNSLOPE OF THE ROADWAY



PHOTO 4 AN EROSION GULLY ON THE ROADWAY DOWNSLOPE TREATED WITH RIPRAP



PHOTO 5 CRACK IN THE BACKSLOPE ABOVE THE BIN WALL



PHOTO 6 BULGE IN THE EAST SECTION OF THE BIN WALL