



Pavement crack west side looking southeast



Light scarp forming





Northeast sink hole



West culvert outlet scour.





Surface disturbance by track equipment.



South ditch – water accumulation





New ponded water east of the abandoned culvert



Ponded water at the abandoned culvert inlet area