



Pavement crack west side looking southeast



West culvert outlet scour.





Slump scarp forming down slope of the west culvert.



Main ponded water location looking north.





Ponded water east of the abandoned culvert



North side sinkhole.