



Photo 1. Pavement distress area (looking east), note pavement dips at the centre (2005).



Photo 2 – Pavement cracks (2005).



Photo 3 – South side sinkhole (2005).



Photo 4 – North side sinkhole (2005).



Photo 5 – Pond water at the blocked culvert inlet location (2005).



Photo 6 – Subhorizontal drains manhole
(photo taken two month after the site visit) (2005).



Photo 7 – Gabion outfall structure
(photo taken two month after the site visit) (2005).