



Photo 1. Pavement distress area (looking east), May 18, 2006.



Photo 2 – Closer view of a pavement crack, May 18, 2006.



Photo 3 – Dip section on the north side slope (west end of site), May 18, 2006.



Photo 4 – New culvert inlet and drainage channel (south of highway),  
May 18, 2006.





Photo 5 –New culvert outlet and drainage channel (north of highway), May 18, 2006



Photo 6 – Subhorizontal drain man access points, (note the knocked down section of the silt fence), May 18, 2006.





Photo 7 –West man access point producing water, May 18, 2006.



Photo 8 – Gabion outfall structure, May 18, 2006.