



Photo 1 - Pavement distress area (looking east).



Photo 2 – Climbing lane fill (note the instrumentation being protected).



Photo 3 – Sideslope fill oversteepened at the culvert outlet location.



Photo 4 – West collection point subdrains.



Photo 5 – Gabion wall interface erosion.



Photo 6 - Collection points east and west outlet (note that despite not currently producing water the east outlet shows signs of water stain below on the culvert).