



Photo 1: Lightly vegetated south sideslope at east flank of site; note pavement dip in Hwy 39:06 at west flank



Photo 2: Rip-rap armoring does not extend to toe of slope at outlet of culvert at east portion of site



Photo 3: Inlet of culvert on east portion of slide above base of ditch



Photo 4: Pavement cracking at west flank of slide area sealed in 2010



Photo 5: Pavement cracking through sealant



Photo 6: Gabion baskets erosion protection at Modeste Creek