



Photo 1 - Looking east at the re-aligned guard rails, June 7, 2006.



Photo 2 - Looking east possible slide crack, June 7, 2006.



Photo 3 - Looking west at edge cracks over culvert, June 7, 2006.



Photo 4 - Looking north at water ponded in culvert, June 7, 2006.



Photo 5 - Looking north at subdued shallow slump Area, June 7, 2006.



Photo 6 - Looking north at the top of north embankment slope, June 7, 2006.



Photo 7 - Looking north - ponded water at toe of north embankment slope, June 7, 2006.