



Photo 1

Looking east along roadway; note crack along pavement



Photo 2

Repaired slope looking northwest



Photo 3
Profile of repaired slope