



Photo 1 - Culvert outlet at Station 42+600, looking southeast.



Photo 2 - Sinkhole on the west slope, near the culvert alignment.





Photo 3 - New slump on the west sideslope, looking east.



Photo 4 - Ditch erosion, looking south.



Photo 5 - View of shallow backslope failures at the south end of the site, looking northwest.



Photo 6 - Backslope failures on the west side of the highway, looking southwest.





Photo 7 - Shale Slope at Station 43+200, looking northwest.



Photo 8 - Shale Slope at Station 43+200.