



Photo 1 – Shallow slope failures on the south end of the site, looking west.



Photo 2 – Ditch erosion on the south end of the site, looking north.





Photo 3 – Earthworks for new culvert installation, looking towards the outlet.



Photo 4 – Earthworks for new culvert installation, looking towards the inlet.





Photo 5 – Steep cut west of the highway near the culvert outlet, looking southeast.



Photo 6 – View of open cut excavation at the culvert outlet, looking southeast.



Photo 7 - View of open cut excavation at the culvert inlet, looking northwest.



Photo 8 - Shale Slope at Station 43+200, looking southeast.