



Photo 1 – Looking west at shallow west backslope failures on the south end of the site.



Photo 2 – Looking north at east ditch erosion at the south end of the site.





Photo 3 – Looking west toward culvert outlet along west sideslope.



Photo 4 – Looking north at east sideslope above culvert inlet.





Photo 5 – Looking north along east guardrail. Note deflection in guardrail at gully.



Photo 6 – Looking southeast at culvert outlet. Note erosion in riprap on right side of the culvert.





Photo 7 – Looking northwest at culvert inlet. Note erosion to right of culvert above the riprap.



Photo 8 – Looking southeast at shale slope at km 43.2.