THURBER ENGINEERING LTD.



PHOTO 1: Looking west at south sideslope of highway embankment



PHOTO 2: Shallow slump near top of highway sideslope



PHOTO 3: Sink hole above culvert alignment



PHOTO 4: Erosion channel along flank of slide block



PHOTO 5: Looking northeast at severe slumping above culvert extension outlet



PHOTO 6: Culvert extension outlet



PHOTO 7: Severe slumping at and downslope of culvert extension outlet