



Photo 1 - Looking east along the highway over the Grimms Creek site area. Note the ACP patch and the dip in the highway.



Photo 2 – Looking southeast at the new culvert outlet area.





Photo 3 - Looking southwest at the old culvert outlet area.



Photo 4 - Looking west along the highway over the site area.





Photo 5 - Looking north at the culvert inlet area.



Photo 6 - Looking west across the new culvert outlet. It is about 20% full of sediment.





Photo 7 – Looking south at the inlet area and upstream embankment slope.



Photo 8 - Looking northeast at the old culvert outlet.