



Photo 1 - Looking east along the highway over the Grimms Creek site area.
Note the ACP patches and the dip in the highway.



Photo 2 – Looking southeast over the downstream embankment and the new culvert outlet area.



Photo 3 - Looking southeast at the culvert inlet area.



Photo 4 - Looking east at a 5 m long x 1 m deep erosion gully that has formed on the east of the channel in front of the culvert inlet.



Photo 5 - Looking north along the eroded channel upstream of the culvert inlet.



Photo 6 – Looking west across the downstream highway embankment.
Note the lack of grass growth along the shallow slide scarp.



Photo 7 - Looking west across the new culvert outlet. It is about 30% full of sediment.



Photo 8 - Looking east across the downstream embankment.