



Photo 1 - View of slope failure, looking south.



Photo 2 - View of slope failure including toe roll and ditch, looking southeast.



Photo 3 - View of slope failure, looking north.



Photo 4 - View of slope failure showing geotextile mesh still in place, looking northwest.



Photo 5 - View of backscarp showing continued seepage, looking southwest.



Photo 6 - View of crack located about 60 m east of main slope failure.