



**Photo S2-1 – June 2009**

Facing westbound across the S2-Priddis site. The settlement and cracking along the north/downslope edge of the highway has been repaved since the 2008 inspection, however the some cracking appears to be re-forming again.



**Photo S2-2 – June 2009**

Facing eastbound across the S2-Priddis site. The settlement and cracking along the north/downslope edge of the highway is visible as is the vertical deflection of the guardrail.



**Photo S2-3 (top) – June 2009**

Facing westbound from the east flank of the slide. No significant changes from the 2008 inspection.

**Photo S2-4 (bottom) – June 2009**

Facing eastbound from the west flank of the slide. No significant changes from the 2008 inspection.





**Photo S2-5 – June 2009**  
An erosion gully that has formed beneath the guardrail and runs towards the downslope. The upslope extent has revealed a pile or other retaining structure.