



Photo S2-1 (June 2012)
– Facing westbound along the downslope edge of the road along the pile wall area. The highway surface here has been recently paved and the guard rail replaced.



Photo S2-2 (June 2012) – Facing eastbound along the pile wall area. Minor cracking is visible on the shoulder edge of the recent overlay.



Photo S2-3 (June 2012) –
Facing eastbound along
the downslope shoulder of
the highway from the west
end of the landslide area.



Photo S2-4 (June 2012) –
Facing eastbound at the
slope below the highway in
the landslide area. The
slope appears to be in
similar condition as was
observed in 2011.