



**Photo S2-1 (May 2013)** – Facing westbound along the downslope edge of the road along the pile wall area. Cracks in the asphalt had formed through the 2013 overlay between the guardrail and white line.



**Photo S2-2 (May 2013) –**  
Facing eastbound along  
the pile wall area.



**Photo S2-3 (May 2013) –**  
Facing eastbound along  
the downslope shoulder of  
the highway from the west  
end of the landslide area.



**Photo S2-4 (May 2013) –** Facing eastbound at the slope below the highway in the landslide area. The slope appears to be in similar condition as was observed in 2012.