



Photo S3-1 (top) – June 2009
Looking to the southeast with
the recent overlay and
repaired ditch visible and SI #4
in the foreground.

Photo S3-2 (left) – June 2009
Looking northwest towards the
recent overlay.



Photo S3-3 – June 2009
A closer view of the repaired ditch area. The 2008 inspection noted a scarp through the ditch berm that has been graded out by the recent repair. Vegetation needs to be established on the freshly graded fill.



Photo S3-4 – June 2009
Looking towards the south with SI #5 visible. The small scarps appear to be in the same condition as was observed in 2008.



Photo S3-5 – June 2009
A close-up view of the ditch repair with the liner visible. SI #2 is painted on the upslope edge of the ditch.