



Photo 1 – Facing northeast down a gully in the southern portion of the slide area. May 2001 photo.



Photo 2 – Facing northeast down the same gully, June 2000 photo.



Photo 3 – Facing south up a gully in the southern portion of the slide area. May 2001 photo.



Photo 4 – Facing south up the same gully, June 2000 photo.



Photo 5 – Looking southeast across scarp and slide area.



Photo 6 – Looking north across scarp and slide area.



Photo 7 – Detail of scarp area showing ongoing oversteepening and toppling of portions of the crest.



Photo 8 – Looking northwest at slide area from toe. Islands/bars in stream are possibly eroded remnants of previous landslide blocks and are protecting current toe from erosion.



CG25132

Alberta Transportation
Southern Region Landslide Monitoring Program
Spring 2001 Assessment Report

Site S4 – Willow Creek