



Photo S4-1 (upper left) – May 2006 – facing north across the area where the landslide scarp has retrogressed further past the fenceline and towards the road since the 2005 inspection.

Compare with Photo S4-3 which shows the same area as it appeared in June 2005.



Photo S4-2 (upper right) – May 2006 – facing south across the area where the landslide scarp has retrogressed further past the fenceline and towards the road since the 2005 inspection.

Compare with Photo S4-3 which shows the same area as it appeared in June 2005.



Photo S4-3 (lower left) – June 2005 – point of maximum slope crest retrogression towards the road as of June 2005.



Photo S4-4 (upper left) – May 2006 – facing south across the landslide area. Note the portion of the toe of the landslide that thrust outwards into the creek channel. The material that was thrust into the creek channel had a “flowed” appearance.

Photo S4-5 (upper right) – May 2006 – facing south across the landslide area.

