Alberta Transportation Southern Region Geohazard Assessment 2012 Annual Inspection Report Site S4: Highway 2:08, Willow Creek November 2012 Page 8





## Photo S4-1 (June 2011) -

Facing north across the soil nail repair area in 2011, for comparison with 2012 conditions (refer to Photo S4-2).



## Photo S4-2 (June 2012) -Taken from near the same location as Photo S4-1. Note the displacement of the stake visible in the foreground of the photos, which indicates a retrogression. Continued retrogression at the slope crest, as well as disturbance of the vegetation by soil flows has occurred. Overall the slope appears more vegetated and stable than previous years.








Photo S4-3 (June 2012) – Facing south at the slide area. The instabilities in the upper, steeper portions of the slope are mostly unchanged from 2011 apart from settlement of the larger blocks. Retrogression of the slide continues to occur with large blocks sliding down and adding to the slide mass although at a seemingly slower rate than observed previously. Alberta Transportation Southern Region Geohazard Assessment 2012 Annual Inspection Report Site S4: Highway 2:08, Willow Creek November 2012 Page 10





## Photo S4-4 (June 2012) -

Facing north at the slide area with a view of the lower slope and river bank. Note the vane damage and the improved vegetation cover.