Alberta Transportation Southern Region Geohazard Assessment 2013 Annual Inspection Report Site S4: Highway 2:08, Willow Creek December 2013 Page 8





Photo S4-1 (May 2013) – Facing north across the area to the south of the soil nail repair area. The crest is now coincident with the old SI installations from ongoing retrogression.



## Photo S4-2 (May 2013) – Facing southwest at the slide area within the soil nailed area. The instabilities in the upper, steeper portions of the slope are mostly unchanged from 2012. Retrogression of the slide continues to occur with blocks sliding down and adding to the slide mass although at a seemingly slower rate than observed previously.

Alberta Transportation Southern Region Geohazard Assessment 2013 Annual Inspection Report Site S4: Highway 2:08, Willow Creek December 2013 Page 9





Photo S4-3 (May 2013) – Facing west at the headscarp within the soil nailed slide area. There was visible seepage noted approximately 1 m below the crest.



Photo S4-4 (May 2013) – Standing on the south side of the erosion gully at the south end of the site, looking towards the northeast at a recent translational slide on the north side-slope. The extents and direction of the failure are outlined in red.

Alberta Transportation Southern Region Geohazard Assessment 2013 Annual Inspection Report Site S4: Highway 2:08, Willow Creek December 2013 Page 10





Photo S4-5 (May 2013) -

Facing north at the slide area with a view of the lower slope and river bank. Note the sedimentation within the vanes and the improved vegetation cover.