



Photo S5-1 (May 2013) –
A general view of the site area facing towards the east, illustrating the extent of the wall settlement, undermined guardrail and the exposed soil nails.



Photo S5-2 (May 2013) –
Standing in the eastbound lane facing southwest at the subtle pavement cracking observed northeast of the diversion barriers and retaining wall.



Photo S5-3 (May 2013) – Standing on the south road shoulder looking towards the southwest at the headscarp retrogression into the road surface and retaining wall.



Photo S5-4 (June 2011) –
An active scarp at the west slide flank noted during the 2011 inspection. Refer to Photo S5-5 for comparison from the 2013 inspection.



Photo S5-5 (May 2013) –
Looking towards the same slide area as Photo S5-4. The exposed soil has eroded but the condition is generally unchanged.