



Photo 1 – October 2001 photo of tension cracks in the settlement/cracking area that was previously identified and investigated in the summer of 2001. The rate of movement and cracking in this area appeared to accelerate in the late summer/fall of 2001. This area was repaved in October 2001 after this photo was taken.



Photo 2 – Another view of the settlement/cracking area before repaving in October 2001.



Photo 3 – Fresh cracks in the repaved settlement/cracking area, as seen in May 2002.



Photo 4 – New crack extending northeast/southwest across the road, approximately 80 m south of the settlement/cracking area shown in Photos 1 to 3. May 2002 photo.





Photo 5 – Another view of the new crack. May 2002 photo.