



Photo S8-1 (upper left) – May 2006 – facing south along the northern area of the site. New cracking observed in the previously-noted cracking and settlement area. The visible cracking has developed since the area was repaved after the 2005 inspection.



Photo S8-2 (upper right) – May 2006 – facing south along the northern area of the site. Another view of the new cracking noted in previous cracking and settlement area.



Photo S8-3 (lower left) – May 2006 – new crack in the road surface approximately 12 m south of the estimated north edge of the area that was repaved since the June 2005 inspection.



Photo S8-4 (lower right) – May 2006 – facing north along the southern area of the site. No new cracking or settlement was noted in this area.