



Photo S8-1 (top) – June 2009
Road surface cracking at the south end of the site around SI 2002-1.



Photo S8-2 (bottom) – June 2009
Facing northbound across the north end of the site, with cracking noted in the September 2008 asphalt overlay. See the site plan on Figure S8-1 for further illustration.



Photo S8-3 – June 2009

Facing southbound across the north end of the site, with cracking noted in the September 2008 asphalt overlay. See the site plan on Figure S8-1 for further illustration.