



Photo S8-1 (June 2012) - Facing north along the west edge of the road surface at the north end of the site. This area had the most significant cracking following a similar pattern as has been observed during previous inspections. The road surface has been smoothed over from recent milling work.



Photo S8-2 (June 2012) - Facing north from the middle of the site. The amount of additional cracking in the road surface is relatively minor, and follows a similar pattern as has been observed during past inspections.



Photo S8-3 (June 2012) -
Facing southeast at the
visible settlement in the
upslope lane at the north
end of the site.